


**Form No. - 37**  
(Prescribed under Rule 12-B )

**Register containing particulars of monitoring of working environment required under section 7-A(a)(e)**

- 1.Name of the Department/Plant - Liquid Plant
- 2.Raw Material,by products and finished products involving in the process :
3. Particulars of sampling

S.No.	Location / Operation mentioned	Identified contaminant	Sampling Instrument Used	Airborne Contamination		Average conc.
				No. of samples	Range	mg/m3
1	2	3	4	5	6	7
1	Liquid Plant	NH <sub>3</sub>	Handy Sampler using impinger tubes	1	-	0.02

TWA conc. (as given in 2nd Schedule)	Reference Method	Number of workers exposed at the location being monitored	Remarks	Signature of person taking samples	Name (in Block Letter)
8	9	10	11	12	13
18 mg/m3	Spectrophot-ometric Method	10	The Result is Within the Limit		Mr.Javed Haveliwala


Work Place Monitoring done at M/s. Jubilant Life Sciences Ltd., in the month of **January - 2020** by Kadam Environmental Consultants, Vadodara. (dtd.24.01.2020)

**Form No. - 37**  
(Prescribed under Rule 12-B)

**Register containing particulars of monitoring of working environment required under section 7-A(a)(e)**

- 1.Name of the Department/Plant - Liquid Plant
- 2.Raw Material,by products and finished products involving in the process :
3. Particulars of sampling

S.No.	Location / Operation mentioned	Identified contaminant	Sampling Instrument Used	Airborne Contamination		Average conc.
				No. of samples	Range	mg/m3
1	2	3	4	5	6	7
2	Liquid Plant	HCL Fumes	Handy sampler using impinger tubes	1	-	0.08

TWA conc. (as given in 2nd Schedule)	Reference Method	Number of workers exposed at the location being monitored	Remarks	Signature of person taking samples	Name (in Block Letter)
8	9	10	11	12	13
7 mg/m3	Titrimetric method	25 - 30	-		Mr.Javed Haveliwala


Work Place Monitoring done at M/s. Jubilant Life Sciences Ltd., in the month of **January - 2020** by Kadam Environmental Consultants, Vadodara. (dtd.24.01.2020)

**Form No. - 37**  
(Prescribed under Rule 12-B )

**Register containing particulars of monitoring of working environment required under section 7-A(a)(e)**

- 1.Name of the Department/Plant - Liquid Plant
- 2.Raw Material,by products and finished products involving in the process :
3. Particulars of sampling

S.No.	Location / Operation mentioned	Identified contaminant	Sampling Instrument Used	Airborne Contamination		Average conc.
				No. of samples	Range	mg/m3
1	2	3	4	5	6	7
3	Liquid Plant	VOC	Rubber Bladder With Suction Pump	1	-	13.99

TWA conc. (as given in 2nd Schedule)	Reference Method	Number of workers exposed at the location being monitored	Remarks	Signature of person taking samples	Name (in Block Letter)
8	9	10	11	12	13
	Gas Chromatography Method	10			Mr.Javed Haveliwala


Work Place Monitoring done at M/s. Jubilant Life Sciences Ltd., in the month of **January - 2020** by Kadam Environmental Consultants, Vadodara. (dtd.24.01.2020)

**Form No. - 37**  
(Prescribed under Rule 12-B)

**Register containing particulars of monitoring of working environment required under section 7-A(a)(e)**

- 1.Name of the Department/Plant - Liquid Plant
- 2.Raw Material,by products and finished products involving in the process :
3. Particulars of sampling

S.No.	Location / Operation mentioned	Identified contaminant	Sampling Instrument Used	Airborne Contamination		Average conc.
				No. of samples	Range	mg/m3
1	2	3	4	5	6	7
1	Liquid Plant	NH <sub>3</sub>	Handy Sampler using impinger tubes	1	-	0.02

TWA conc. (as given in 2nd Schedule)	Reference Method	Number of workers exposed at the location being monitored	Remarks	Signature of person taking samples	Name (in Block Letter)
8	9	10	11	12	13
18 mg/m3	Spectrophot-ometric Method	10	The Result is Within the Limit		Mr.Javed Haveliwala


Work Place Monitoring done at M/s. Jubilant Life Sciences Ltd., in the month of **January - 2020** by Kadam Environmental Consultants, Vadodara. (dtd.24.01.2020)

**Form No. - 37**  
(Prescribed under Rule 12-B )

**Register containing particulars of monitoring of working environment required under section 7-A(a)(e)**

- 1.Name of the Department/Plant - Liquid Plant
- 2.Raw Material,by products and finished products involving in the process :
3. Particulars of sampling

S.No.	Location / Operation mentioned	Identified contaminant	Sampling Instrument Used	Airborne Contamination		Average conc.
				No. of samples	Range	mg/m <sup>3</sup>
1	2	3	4	5	6	7
2	Liquid Plant	HCL Fumes	Handy sampler using impinger tubes	1	-	0.08

TWA conc. (as given in 2nd Schedule)	Reference Method	Number of workers exposed at the location being monitored	Remarks	Signature of person taking samples	Name (in Block Letter)
8	9	10	11	12	13
7 mg/m <sup>3</sup>	Titrimetric method	25 - 30			Mr.Javed Haveliwala


Work Place Monitoring done at M/s. Jubilant Life Sciences Ltd., in the month of **January - 2020** by Kadam Environmental Consultants, Vadodara. (dtd.24.01.2020)

**Form No. - 37**  
(Prescribed under Rule 12-B )

**Register containing particulars of monitoring of working environment required under section 7-A(a)(e)**

- 1.Name of the Department/Plant - Liquid Plant
- 2.Raw Material,by products and finished products involving in the process :
3. Particulars of sampling

S.No.	Location / Operation mentioned	Identified contaminant	Sampling Instrument Used	Airborne Contamination		Average conc.
				No. of samples	Range	mg/m3
1	2	3	4	5	6	7
3	Liquid Plant	VOC	Rubber Bladder With Suction Pump	1	-	13.99

TWA conc. (as given in 2nd Schedule)	Reference Method	Number of workers exposed at the location being monitored	Remarks	Signature of person taking samples	Name (in Block Letter)
8	9	10	11	12	13
	Gas Chromatography Method	10			Mr.Javed Haveliwala

Work Place Monitoring done at M/s. Jubilant Life Sciences Ltd., in the month of **January - 2020** by Kadam Environmental Consultants, Vadodara. (dtd.24.01.2020)